



10-671534

2/10

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of

Donna K. BARTON et al

Patent No: 6,814,706 **B2**

Issued: November 9, 2004

For: SKIN PATCH INCLUDING A TEMPERATURE
SENSOR

Certificate
NOV 23 2004
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 CFR 1.322(a))

COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450

Attention: Patent Issue Division
Decision and Certificate of Correction Branch

Sir:

It is requested that a Certificate of Correction be issued in accordance with the form PTO-1050 that is enclosed herewith in duplicate.

The column and line numbers where the errors occur in the issued patent are specified below. The source of the correction is indicated in parentheses following the correction.

Column 6, line 60, "secon" should be deleted and replaced with --second-- (Reply to the Office Action Mailed March 25, 2004, new claim 21 (renumbered for publication as claim 18).)


Column 7, line 7, --and the perforations in the flexible circuit substrate-- should be inserted after "substrate". (Reply to the Office Action Mailed March 25, 2004, new claim 22 (renumbered for publication as claim 19).)

This patent is assigned of record to Mini-Mitter Company, Inc., the assignment having been recorded on February 8, 2002 at Reel 012577, Frame 0443.

This request is made by the undersigned as attorney for the patentee/assignee under the Power of Attorney that was signed on February 7, 2002 and is of record in the Patent and Trademark Office.

Please send the certificate to the address indicated below.

Respectfully submitted,




John Smith-Hill
Reg. No. 27,730

SMITH-HILL & BEDELL, P.C.
12670 N.W. Barnes Rd., #104
Portland, Oregon 97229
(503) 574-3100
Docket: MINI 2195
Postcard: 11/04-16

Certificate of Mailing

I hereby certify that this correspondence is being deposited with sufficient postage as first class mail with the United States Postal Service in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, Virginia 22313-1450, on this 15th day of November, 2004.



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,814,706 *B2*

DATED : November 9, 2004

INVENTOR(S) : Donna K. Barton, Florian G. Bell, Jesse S. Laird and Thomas Clifton Meyer

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 60, "secon" should be deleted and replaced with --second--.

Column 7, line 7, --and the perforations in the flexible circuit substrate-- should be inserted after "substrate".

MAILING ADDRESS OF SENDER:

SMITH-HILL AND BEDELL, P.C.
12670 N.W. Barnes Road, #104
Portland, Oregon 97229

PATENT NO. 6,814,706
ATTORNEY DOCKET MINI 2195

NOV 23 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,814,706 *B2*

DATED : November 9, 2004

INVENTOR(S) : Donna K. Barton, Florian G. Bell, Jesse S. Laird and Thomas Clifton Meyer

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 60, "secon" should be deleted and replaced with --second--.

Column 7, line 7, --and the perforations in the flexible circuit substrate-- should be inserted after "substrate".

MAILING ADDRESS OF SENDER:

SMITH-HILL AND BEDELL, P.C.
12670 N.W. Barnes Road, #104
Portland, Oregon 97229

PATENT NO. 6,814,706
ATTORNEY DOCKET MINI 2195

NOV 23 2004